



The Willow Enviro team was instructed to carry out the safe removal and disposal of over 280m², Asbestos containing textured coated ceilings and walls.



Site Location: Southend-On-Sea

Duration: 5 Days

Asbestos Containing Material: Textured Coating

All works was carried out under controlled conditions with ASB1 Notification in place. Works was completed to client's complete satisfaction.

WILLOW-ENVIRO.CO.UK



WILLOW-ENVIRO.CO.UK

